

Group / Tag	Species	Ht (m)	Dia (mm)	Age Class	Condition	Comments	Recommendations	Timescale
Group 1	Cherry avenue	Up to 6	Up to 250	Semi mature	Good	Evenly spaced avenue lining driveway to car park and club house. Trees developing well. Have been pruned and shaped to maintain low height.		
Group 2	Ash, elm	Up to 12	Up to 300	Semi mature	Fair - Dead	Clump of predominantly ash at site entrance. End tree overhangs driveway. Ivy becoming well established on stems. Dead elm has collapsed into trees. Ash currently ADD Class 1.	Monitor for Ash Dieback Disease.	
Group 3	Silver birch, ash, elm, Sycamore	Up to 15	Up to 500	Mature - Semi mature	Fair - Dead	Predominantly birch edge trees overhanging practice area. Trees growing on embankment of Deeside Way. 2 birch blew over in storm. Stumps remain. Ash currently ADD Class 1.	Monitor for Ash Dieback Disease.	
Group 4	Sycamore, cherry, oak, rowan, alder, ash, lime, larch	Up to 18 (larch)	550	Mature - Semi mature	Fair	Edge of woodland area adjacent to car park. Semi mature broadleaf trees on mown grass. Larger larch along boundary fence. Open grown, older cherry tree near car park has decay and pholiota fungal bodies at base. Nearby mature sycamores with ivy on trunk at woodland edge with Deeside Way. Dense group of cherries on embankment above putting practice green.		
Group 5	Sitka spruce, Lawson cypress, cherries	Up to 15	Up to 450	Semi mature	Fair	Dense group of trees adjacent to 1st tee. Spruce bleeding from lower trunk.		
Group 6	Beech	Up to 25	Up to +1000	Mature - Semi mature	Fair - Poor	Strip of predominantly mature beech adjacent to 1st tee. Semi-mature trees at edge of mature canopy. Trees within falling distance of tee, track and Deeside Way. Large decaying wound on lower trunk of first tree at northern end next to track. 2 Severely decayed and dying trees present at edge but with bias away from tee. Dense holly making access to base of trees near Deeside Way difficult. Large beech surrounded by dense holly has recently shed large branch. Remaining limb is severely wounded. Access beneath the trees is restricted by presence of holly. Old trees may continue to shed branches onto infrequently accessed area.		
Group 7	Scots pine, beech, cherry, larch, lime	Up to 25	Up to 800	Mature - Semi mature	Fair - Poor	Dense block of woodland on embankment at northern site boundary. Beech trees around edge which overhangs infrequently accessed rough ground to the north and golf course track to the south. Closely spaced pines and occasional sycamore and larch within interior of woodland. Dense holly understorey. Small dead beech next to track poses little threat to safety. Row of mature beech and lime along southern boundary with water course. Moderate deadwood overhanging vehicle track. Elm trees, tagged 405, has been killed by Dutch Elm disease and could be retained to provide biodiversity.		

Group / Tag	Species	Ht (m)	Dia (mm)	Age Class	Condition	Comments	Recommendations	Timescale
Group 8	Sitka spruce, Scots pine, beech, ash, Sycamore	Up to 27	Up to 700	Mature - Semi mature	Fair - Poor	Adjoins group 7. Edge of tall spruce overhanging site boundary with infrequently accessed rough ground to north. Ground beneath pines is compacted in places and roots have been severed where track is formed. Mature limes and beech along southern boundary of group with water course. Trees at eastern end of group overhanging neighbouring property. Tall spruce tree close to house at Cults Farm has been removed. Large piles of turf and branches with woodland at eastern end next to water course where dead tree is present. Includes tagged trees 404, 512 and 566.	Monitor for Ash Dieback Disease.	
Group 9	Ash, birch, oak, Lawson cypress	Up to 10	Up to 450	Semi mature	Fair - Poor	Strip of trees, dense in places. Adjacent to green keepers sheds and yard. Ivy well established on some trees. Groups of oak developing well on mown grass. Cherries along boundary with houses. Very close to houses in places Overhanging beech hedge. ADD Class 1.	Monitor for Ash Dieback Disease.	
Group 10	Lawson cypress	Up to 10	Upto 300	Semi mature	Poor	Multi stemmed cypress at entrance green keepers buildings and row of cypress extending to the south of the buildings and adjoining Group 11. Planted as hedge but becoming tall. Roots exposed by excavation in embankment. 3 blew over during winter 21/22 storm.	Reduce height and clip annually to maintain as hedge.	Within 6 months
Group 11	Beech and other broadleaves	24	Up to +1000	Mature	Fair - Poor	Dense area of predominantly beech with occasional sycamore, and ash. Forming closed canopy on steep embankment. Trees within interior and along top of embankment are infrequently accessed. Increased ground levels at base of trees overhanging greenkeepers facility. Grass clippings have been tipped at base of trees adjacent to driving range. Trees at southern edge overhang small water course and edge of golf course. Two alders growing from edge of water course are beginning to uproot and appear to be gradually falling towards the infrequently accessed margin of the golf course. Large trees with storm damaged limbs overhanging golf course and track. Large decayed and structurally defective trees present on steep embankment are subject to very occasional access. Boundary with Camphill Estate is formed by track. ADD Class 1.	Monitor for Ash Dieback Disease.	
Group 12	Silver birch	Up to 16	Up to 500	Mature - Semi mature	Fair - Poor	Row of closely spaced birch with single cypress, and occasional hawthorn and hazel lining section of western site boundary. Ground disturbance at base of cypress at northern end.		
Group 13	Mixed conifers and broadleaves	Up to 25	Up to 900	Mature - Semi mature	Fair - Poor	Dense woodland block within Camphill Estate and overhanging site boundary at 4th tee and fairway. Large mature conifers and broadleaves. Considerable standing water within woodland at time of survey. One large Scots pine overhanging track within golf course. Group becomes pure Scots pine at southern end next to 4th tee.		

Group / Tag	Species	Ht (m)	Dia (mm)	Age Class	Condition	Comments	Recommendations	Timescale
Group 14	Mature Sitka spruce, Scots pine and larch. Semi-mature cypress and mixed broadleaves	Up to 25	Up to 750	Mature - Semi mature	Fair	Adjacent to 6th fairway. Mature conifers planted in closely spaced groups of similar. One individual, open grown spruce also present. Dead cypress have been removed. Healthy cypress also present. Mixed broadleaves developing well.		
Group 15	Sitka spruce	Up to 24	Up to +1000	Mature	Good - Fair	Strip of 14 lining 3rd fairway. Occurs as a row of 10 with a significant gap to 4 more. Well formed but often with sparse crowns. Tapered trunks with swollen bases. Roots at surface frequently damaged by mower.		
Group 16	Mixed broadleaves	Up to 7	Up to 250	Semi mature	Fair - Poor	Bushy semi mature trees along river bank. Maybe beyond site boundary.		
Group 17	Sitka spruce with semi mature mixed broadleaves	Up to 28	1000+	Mature - Semi mature	Good - Poor	Very large and impressive spruce surrounded by semi mature broadleaf trees. Invasive Himalyan balsam previously noted at base of spruce. Area of tipped turf and soil beneath canopy. Dead elm at edge of semi-mature group has succumbed to Dutch Elm Disease.		
Group 18	Mature Sitka spruce with semi mature mixed broadleaves and cypress	Up to 24	Up to +1000		Good - Poor	Lining 5th fairway. Well spaced spruce planted as double row. Sparse crowns and well tapered trunks. Large spruce surrounding 5th green. Scots pine with decay in large pruning wound next to 4th green.		
Group 19	Sitka spruce and Larch	Up to 28	Up to 750	Mature	Good - Fair	Clump of 8 closely spaced spruce between 5th and 6th fairways. Suppressed larch trees beneath dominant trees.		
Group 20	Mature Sitka spruce	Up to 24	Up to +1000	Mature - Semi mature	Fair - Poor	Single row of mature spruce lining the 6th fairway. 4 large spruce next to the 6th tee and 2nd green. Sparse crowns.		
Group 21	Mature Scots pine and larch with semi mature broadleaf trees	Up to 18	Up to 500	Mature - Semi mature	Fair - Poor	Group of mature conifers with semi mature Norway maples and rowans. Very hollow alder next to water channel is sheltered within group. 2 badly storm damaged mature pines recently removed and exposing remaining pine which displays minor storm damage and moderate deadwood.		

Group / Tag	Species	Ht (m)	Dia (mm)	Age Class	Condition	Comments	Recommendations	Timescale
Group 22	Mature conifers with semi mature broadleaf trees	Up to 24	Up to +1000	Mature - Semi mature	Good - Fair	Row of spruce between 6th and 8th holes. Clump of semi mature broadleaf trees generally developing well at either end.		
Group 23	Cypress	10	400	Semi mature	Fair - Dead	Two dead cypress next to 7th fairway have been removed.		
Group 24	Willow and Poplar	Up to 10	Up to 300	Semi mature	Good - Poor	4 widely spaced semi mature trees on wet ground. In standing water at the time of survey.		
Group 25	Firs in tree nursery	<1	10	Seedling	Poor	Numberous dead and remaining dying due to severe roe deer grazing and wet ground conditions.		
Group 26	Sitka spruce and Douglas fir	Up to 22	Up to 850	Mature	Fair	3 mature Sitka spruce and one semi-mature Douglas fir near 7th green.		
Group 27	Semi mature broadleaves	Up to 9	Up to 300	Semi mature	Good - Fair	Norway maple, sycamore and beech next to 7th green. One maple displays a column of dying bark (410).		
Group 28	Scots pine	Up to 22	Up to 600	Mature	Fair	Dense clump of 12 individuals between 7th and 8th greens. Mature pines shading 8th green and impacting grass health. Restricted spread with deadwood on straight lower trunks.		
Group 29	Scots pine and larch	Up to 12	Up to 200	Semi mature	Fair	Conifers developing well.		

Group / Tag	Species	Ht (m)	Dia (mm)	Age Class	Condition	Comments	Recommendations	Timescale
Group 30	Mixed broadleaves with single mature spruce	Up to 12	Up to 550	Semi mature. Mature lime.	Good - Fair	Lining 18th fairway. Large lime tree near centre developing well. Cherry, oak and maple also present. Large spruce at northern end.		
Group 31	Mature Sitka spruce and pine. Semi mature broadleaves	Up to 26	Up to +1000	Mature - Semi mature	Good - Poor	Surrounding 18th tee. Mature Scots pine near bridge with decay in old pruning wounds and deadwood throughout crown. Spruce is well formed but sparse. Semi mature trees extend next to 2nd fairway and includes sycamores, poplar and twin stemmed decaying alder.		
Group 32	Norway spruce and corsican pine	Up to 18	Up to 400	Semi mature	Fair - Poor	Dense group next to 17th green. Trees of restricted spread with no lower branches. One large multi-stemmed pine next to bunker.		
Group 33	Mixed broadleaves	Up to 16	Up to 500	Semi mature	Fair - Poor	Alder, cherries, rowan, poplars and occasional pine between 15th and 17th fairways. Large number of trees severely damaged at base by mower or grazing animals.	Avoid strimmer damage.	
Group 34	Mixed broadleaves	Up to 14	Up to 500	Semi mature	Fair - Poor	Generally developing well between 3rd tee and 17th fairway. 2 alder (413 and 414) significantly damaged at base and dying.	Avoid strimmer damage.	
Group 35	Mature Scots pine and larch with semi mature broadleaf trees	Up to 24	Up to 900	Mature - Semi mature	Good - Fair	8 large spruce on row between 2nd and 17th fairways. Small group of broadleaves at edge of canopy. Trees at northern end next to green.		
Group 36	Mature Sitka spruce	Up to 22	Up to 950	Mature	Good - Fair	Dense group of 7 next to green.		
Group 37	Mixed semi mature broadleaves and mature conifers	Up to 16	Up to 800	Semi mature - young	Fair - Poor	Oaks developing well. 2 cherries severely decayed at base. Willow and Rowan also present. One short mature spruce with 2 pines at base. Semi mature pine and spruce also present. Scattered trees. Includes dying alder 415.	Avoid strimmer damage.	

Group / Tag	Species	Ht (m)	Dia (mm)	Age Class	Condition	Comments	Recommendations	Timescale
Group 38	Birch, oak, rowan	Up to 11	Up to 600 (birch)	Mature - Semi mature	Fair	Trees on embankment below 1st or 10th tee. Birch at edge of track with recent wound to bark of lower trunk. Oak developing good spreading form. Large clumps of broom present.		
Group 39	Alder	Up to 7	Up to 200	Semi mature	Fair	Trees at base of embankment.		
Group 40	Oak and lime	Up to 18	Up to 650	Mature	Fair	2 adjacent prominent trees next to pond. Oak developing well with spreading crown. Lime is smaller and had been crown reduced.		
Group 41	Mature Sitka spruce	Up to 20	Up to 800	Mature	Fair - Poor	Group of 6 next to 1st green. Well formed but with very sparse crowns.		
Group 42	Leyland cypress, sycamore and rhododendrons	12	350	Semi mature	Fair	6 cypress and one multi stemmed sycamore in prominent elevated location next to first green. Rhododendron around edge.		
Group 43	Mature Sitka spruce with few semi mature confers and broadleaves	Up to 22	Up to 1000	Mature - Semi mature	Good - Fair	Row of well formed and widely spaced spruce trees between 15th and 18th fairways. Occasional semi mature tree present.		
Group 44	Sitka spruce	Up to 24	Up to 750	Mature	Fair - Poor	Dense triple row. Suppressed individuals within interior. Occasional resinous bleeding from trunks. Few semi mature broadleaf trees at southern end. Group considered to be at significant risk of storm damage as has occurred within neighbouring similar Group 45. Trees tagged 1766 to 833 and recorded below.		
Group 45	Sitka spruce	Up to 24	Up to 750	Mature	Fair - Poor	Dense triple row. Suppressed individuals within interior. Occasional resinous bleeding from trunks. Windblown has occurred at northern end bisected the group. Heterobasidion fungal bodies noted at the base of 1717. Trees tagged 1703 to 1765 and recorded below.		

Group / Tag	Species	Ht (m)	Dia (mm)	Age Class	Condition	Comments	Recommendations	Timescale
Group 46	Mature Sitka spruce and pines with semi mature broadleaf trees	Up to 24	Up to 1000	Mature - Semi mature	Good - Poor	Widely spaced row of 6 well formed, but sparse spruce and 4 pines of lesser form. Mixed semi-mature broadleaves in gaps. Trees next to 13th green. Poplar 567 has extensive bark stripping on lower trunk due to roe deer.		
Group 47	Mature Sitka spruce	Up to 24	Up to 1000	Mature	Good	Evenly spaced single row. Well formed trees with dense crowns. Tagged 1681 to 1703. Occasional semi mature broadleaf at edge.		
Group 48	Mixed species	Up to 11	Up to 400	Semi mature	Good - Poor	Dense group with closed canopy and overgrown understorey. Trees developing well and providing good wildlife habitat. Column of dying bark at base of sycamore next to 14th tee.		
Group 49	Alder, ash, yew and willow	Up to 15	Up to 500	Mature - Semi mature	Good - Poor	Few trees on area of rough ground next to water course. Wetland vegetation. Decaying alder at margin of course. Mature spreading yew in good condition.	Monitor for Ash Dieback Disease.	
Group 50	Sitka spruce	Up to 26	Up to +1000	Mature	Fair	Row of 4 in exposed location next to 13th tee. Sparse crowns. Dead tree has been removed.		
Group 51	Mixed semi mature trees	Up to 12	Up to 400	Semi mature	Good to dead	Strips of semi-mature planting along fairways. Generally developing well.		
Group 52	Mature Sitka spruce					Dying trees have been removed		
Group 53	Silver birch	10	200	Semi mature	Good	Trees within ornamental planting next to club house.		

Group / Tag	Species	Ht (m)	Dia (mm)	Age Class	Condition	Comments	Recommendations	Timescale
Group 54	Wild cherry	10	200	Semi mature	Fair - Poor	Dense group next to track.		
Tagged Trees								
401	Silver birch	16	350: 350	Mature	Poor	At site boundary overhanging Deeside Way. Decayed at base with birch polypore on snapped stem. Exposed following recent removal of dead elm. Limited life expectancy. Base obscured by dense holly.		
402	Norway maple	18	500	Mature	Fair	Dead elm overhanging golf course track has been removed exposing maple. Cavity on trunk with good wound wood formation. Additional space for maple to spread and improve in form.		
403	Scots pine	22	650	Mature	Poor	Next to track with bias towards green. Severely storm damage with decay in broken limbs. Woodpecker habitat.		
404	Beech	20	700	Mature	Poor	Large tree at edge of group 8. Overhanging water course with bias towards green. Low vigour. Bark death on lower trunk. Large basal cavity. Relatively sheltered by neighbouring trees.		
405	Wych elm	17	MS 500	Mature	Dead	Standing dead due to dutch Elm Disease. Overhanging infrequently used track. Retain to improve biodiversity.		
410	Norway maple	12	400	Semi mature	Poor	Column of dying bark from base. Limited life expectancy.	Monitor	
416	Ash	14	650	Mature	Fair	In prominent location overhanging frequently used track next to club house. Spread crown with significant tip dieback.	Deadwood. Monitor for Ash Dieback Disease.	Within 6 months
422	Ash	20	400	Early mature	Fair	Group of 5 individuals next to 2nd tee. Have been exposed following removal of dead elm. Broken, hanging branches on largest tree have been pruned.	Monitor for Ash Dieback Disease.	
423	Ash	21	550	Mature	Poor	Top has snapped due to increased exposure to wind following removal of adjacent elms. Long high limb overhanging rough ground appears exposed but with infrequent access below.	Monitor for Ash Dieback Disease.	
424	Scots pine	16	500	Early mature	Fair	Next to 14th fairway. Broken branches in lower crown. Adjacent alders are dying, probably due to composting pile of grass clippings at base.		
425	Alder	10	500	Mature	Poor	In decline next to crossing by 14th green. Dead top and decayed base.	Monitor	

Group / Tag	Species	Ht (m)	Dia (mm)	Age Class	Condition	Comments	Recommendations	Timescale
512	Beech	23	950	Mature	Fair	Large dense crown. Leaning with bias towards tee.		
565	Cypress	12	600	Mature	Fair	Patch of brown foliage in lower crown.		
566	Beech	21	750	Mature	Poor	Declining and with severely decayed trunk. Next to green.		
567	Poplar	12	350	Semi-mature	Poor	Severely grazed at base.		
568	Scots pine	18	900	Mature	Fair	Spreading crown between tee, green and bridge crossing.		
569	Alder	12	350	Mature	Poor	Extensively decayed and hollow at base. Next to green.		
1968	Beech	18	550: 400	Mature	Poor	At edge of woodland. Co-dominat stems has been removed. Will be exposed by removal of dead elms 405.		
Conifers with Group 47								
1681	Sitka spruce	24	850	Mature	Fair	End tree of single row of similar. Good form. Dense crown. Increased ground level at base.		
1682	Sitka spruce	24	950	Mature	Fair	Within single row of similar. Good form. Dense crown.		
1683	Sitka spruce	24	900	Mature	Fair	Within single row of similar. Good form. Dense crown.		
1684	Sitka spruce	24	950	Mature	Fair	Within single row of similar. Good form. Dense crown.		
1685	Sitka spruce	24	950	Mature	Fair	Within single row of similar. Good form. Dense crown.		

Group / Tag	Species	Ht (m)	Dia (mm)	Age Class	Condition	Comments	Recommendations	Timescale
1686	Sitka spruce	24	850	Mature	Fair	Within single row of similar. Good form. Dense crown.		
1687	Sitka spruce	24	800	Mature	Fair	Within single row of similar. Good form. Less dense crown.		
1688	Sitka spruce	24	800	Mature	Fair	Within single row of similar. Good form. Less dense crown.		
1689	Sitka spruce	24	800	Mature	Fair	Within single row of similar. Good form. Dense crown.		
1690	Sitka spruce	24	700	Mature	Fair	Within single row of similar. Good form. Less dense crown.		
1691	Sitka spruce	24	1000	Mature	Poor	Within single row of similar. Good form. Less dense crown. Swollen butt.		
1692	Sitka spruce	25	1000	Mature	Fair	Within single row of similar. Good form. Dense crown.		
1693	Sitka spruce	25	950	Mature	Fair	Within single row of similar. Good form. Dense crown.		
1694	Sitka spruce	24	750	Mature	Fair	Within single row of similar. Good form. Dense crown. Area of compacted ground at base.		
1695	Sitka spruce	24	700	Mature	Fair	Within single row of similar. Good form. Dense crown.		
1696	Grand fir	14	750	Mature	Poor	Within single row of similar. Lesser form forking at <2m. Stunted with dense crown.		
1697	Sitka spruce	22	750	Mature	Fair	Within single row of similar. Good form. Dense crown.		
1698	Sitka spruce	26	850	Mature	Fair	Within single row of similar. Good form. Dense crown.		

Group / Tag	Species	Ht (m)	Dia (mm)	Age Class	Condition	Comments	Recommendations	Timescale
1699	Sitka spruce	26	850	Mature	Fair	Within single row of similar. Good form. Dense crown.		
1700	Lodgepole pine	20	600	Mature	Poor	Within closely spaced single row. Reasonable form. Dense crown.		
1701	Sitka spruce	25	1000	Mature	Fair	Within single row of similar. Good form. Less dense crown. Compacted aggregate path at base. Branches to ground level.		
1702	Scots pine	17	700	Mature	Fair	Spreading crown adjacent to end of row. Next to 2 suppressed Scots pine. Moderate deadwood throughout.		
Conifers within Group 45								
1703	Sitka spruce	9	250	Semi mature	Poor	Very suppressed at edge of group of 4 rows.		
1704	Sitka spruce	20	550	Mature	Fair	Edge tree within group of 4 rows. Roots damaged by mower.		
1705	Sitka spruce	25	650	Mature	Fair	Edge tree within group of 4 rows. Roots damaged by mower.		
1706	Sitka spruce	26	800	Mature	Fair	Edge tree within group of 4 rows. Dense, one-sided crown.		
1707	Sitka spruce	26	600	Mature	Fair	Edge tree within group of 4 rows. Dense, one-sided crown.		
1708	Sitka spruce	26	650	Mature	Fair	Edge tree within group of 4 rows. Dense, one-sided crown.		
1709	Sitka spruce	26	700	Mature	Fair	Edge tree within group of 4 rows. Dense, one-sided crown.		
1710	Sitka spruce	27	600	Mature	Fair	Edge tree within group of 4 rows. Dense, one-sided crown.		
1711	Sitka spruce	27	750	Mature	Fair	Edge tree within group of 4 rows. Dense, one-sided crown.		

Group / Tag	Species	Ht (m)	Dia (mm)	Age Class	Condition	Comments	Recommendations	Timescale
1712	Sitka spruce	27	900	Mature	Fair	Edge tree within group of 4 rows. Dense, one-sided crown. Mower damage to roots.		
1713	Sitka spruce	18	320	Semi mature	Poor	Edge tree within group of 4 rows. Neighbours have blown over. Sparse, one-sided crown.		
1714	Sitka spruce	23	650	Mature	Fair	Edge tree within group of 4 rows. Dense, one-sided crown.		
1715	Sitka spruce	24	900	Mature	Fair	End tree within group of 4 rows. Dense, one-sided crown.		
1716	Sitka spruce					Has been removed 21/22.		
1717	Sitka spruce	27	750	Mature	Poor	Within group of 4 rows. Neighbouring trees have blown over. Very restricted spread few live lower branches. Large heterobasidion annosum fungal bracket between root buttresses.		
1718	Sitka spruce					Has been removed due to exposure and presence of root decay.		
1719	Sitka spruce	24	330	Mature	Poor	Within group of 4 rows. Very restricted spread with no live lower branches.		
1720	Sitka spruce	24	300	Mature	Poor	Within group of 4 rows. Very restricted spread with no live lower branches.		
1721	Sitka spruce	24	360	Mature	Poor	Within group of 4 rows. Very restricted spread with no live lower branches.		
1722	Sitka spruce	24	320	Mature	Poor	Within group of 4 rows. Very restricted spread with no live lower branches.		
1723	Sitka spruce	24	500	Mature	Fair	Within group of 4 rows. Restricted spread with few lower branches.		
1724	Sitka spruce	25	550	Mature	Poor	Within group of 4 rows. Restricted spread with no live lower branches.		

Group / Tag	Species	Ht (m)	Dia (mm)	Age Class	Condition	Comments	Recommendations	Timescale
1725	Sitka spruce	25	550	Mature	Poor	Within group of 4 rows. Restricted spread with few live lower branches.		
1726	Sitka spruce	20	350	Mature	Poor	Within group of 4 rows. Very restricted spread with no live lower branches.		
1727	Sitka spruce	20	340	Mature	Poor	Within group of 4 rows. Very restricted spread with no live lower branches.		
1728	Sitka spruce	25	600	Mature	Poor	Within group of 4 rows. Restricted spread with few live lower branches.		
1729	Sitka spruce	25	800	Mature	Fair	End tree within group of 4 rows. One side, dense crown.		
1730	Sitka spruce	25	650	Mature	Fair	End tree group of 4 rows. Restricted spread with one sided development.		
1731	Sitka spruce	24	360	Mature	Poor	Within group of 4 rows. Very restricted spread with no live lower branches.		
1732	Sitka spruce	20	280	Mature	Poor	Within group of 4 rows. Very restricted spread with no live lower branches.		
1733	Sitka spruce	24	500	Mature	Poor	Within group of 4 rows. Very restricted spread with no live lower branches.		
1734	Sitka spruce	25	400	Mature	Poor	Within group of 4 rows. Very restricted spread with no live lower branches.		
1735	Sycamore	20	350	Semi mature	Poor	Within group of 4 rows. Restricted spread from fork at 3m.		
1736	Sitka spruce	25	400	Mature	Poor	Within group of 4 rows. Very restricted spread with no live lower branches.		
1737	Sitka spruce	24	350	Mature	Poor	Within group of 4 rows. Very restricted spread with no live lower branches.		

Group / Tag	Species	Ht (m)	Dia (mm)	Age Class	Condition	Comments	Recommendations	Timescale
1738	Sitka spruce	25	400	Mature	Poor	Within group of 4 rows. Very restricted spread with no live lower branches.		
1739	Sitka spruce	25	370	Mature	Poor	Within group of 4 rows. Very restricted spread with no live lower branches.		
1740	Sitka spruce	25	330	Mature	Poor	Within group of 4 rows. Very restricted spread with no live lower branches.		
1741	Sitka spruce	22	320	Mature	Poor	Within group of 4 rows. Very restricted spread with no live lower branches.		
1742	Sitka spruce	26	700	Mature	Fair	Within group of 4 rows. Restricted spread with few live lower branches.		
1743	Sitka spruce	25	450	Mature	Poor	Within group of 4 rows. Restricted spread with few live lower branches.		
1744	Sitka spruce	24	400	Mature	Poor	Within group of 4 rows. Restricted spread with few live lower branches. Neighbouring trees have blown over. Small <i>Heterobasidiom annosum</i> fungal body on root 1.5m east of base recorded in February 2014 was not noted during Octobr 2018 survey.		
1745	Sitka spruce					Dead tree has been removed.		
1746	Sitka spruce	27	800	Mature	Fair	End tree within group of 4 rows. Dense, one-sided crown.		
1747	Sitka spruce					Removed.		
1748	Sitka spruce					Removed.		
1749	Sitka spruce					Removed.		
1750	Sitka spruce	25	600	Mature	Poor	Edge tree within group of 4 rows. Dense, one-sided crown. Fork at 9m forming 2 co-dominant leaders.		

Group / Tag	Species	Ht (m)	Dia (mm)	Age Class	Condition	Comments	Recommendations	Timescale
1751	Sitka spruce	24	380	Mature	Poor	Edge tree within group of 4 rows. Restricted, one-sided crown.		
1752	Sitka spruce	26	800	Mature	Fair	Edge tree within group of 4 rows. Dense, one-sided crown.		
1753	Sitka spruce	12	120	Semi mature	Poor	Edge tree within group of 4 rows. Very suppressed and restricted.		
1754	Sitka spruce	26	480	Mature	Fair	Edge tree within group of 4 rows. Dense, one-sided crown.		
1755	Sitka spruce	26	550	Mature	Poor	Edge tree within group of 4 rows. Dense, one-sided crown.		
1756	Sitka spruce	26	800	Mature	Fair	Edge tree within group of 4 rows. Dense, one-sided crown.		
1757	Sitka spruce	26	600	Mature	Fair	Edge tree within group of 4 rows. Dense, one-sided crown.		
1758	Sitka spruce	25	380	Mature	Poor	Edge tree within group of 4 rows. Restricted, one-sided crown.		
1759	Sitka spruce	26	650	Mature	Fair	Edge tree within group of 4 rows. Dense, one-sided crown.		
1760	Sitka spruce	26	800	Mature	Fair	Edge tree within group of 4 rows. Dense, one-sided crown.		
1761	Sitka spruce	26	800	Mature	Poor	Edge tree within group of 4 rows. Dense, one-sided crown. Swollen butt.		
1762	Sitka spruce	26	750	Mature	Poor	Edge tree within group of 4 rows. Dense, one-sided crown.		
1763	Sitka spruce	22	420	Mature	Poor	Edge tree within group of 4 rows. Restricted, one-sided crown.		
1764	Sitka spruce	26	750	Mature	Fair	Edge tree within group of 4 rows. Dense, one-sided crown.		

Group / Tag	Species	Ht (m)	Dia (mm)	Age Class	Condition	Comments	Recommendations	Timescale
1765	Sitka spruce	20	500	Mature	Poor	Edge tree within group of 4 rows. Dense, one-sided crown.		
Conifers within Group 44								
1766	Sitka spruce	24	550	Mature	Fair	Edge tree within group of 4 rows. Dense, one-sided crown.		
1767	Sitka spruce	26	750	Mature	Fair	Edge tree within group of 4 rows. Dense, one-sided crown.		
1768	Sitka spruce	25	650	Mature	Fair	Edge tree within group of 4 rows. Dense, one-sided crown.		
1769	Sitka spruce	25	600	Mature	Fair	Edge tree within group of 4 rows. Dense, one-sided crown.		
1770	Sitka spruce	26	600	Mature	Fair	Edge tree within group of 4 rows. Dense, one-sided crown.		
1771	Sitka spruce	24	450	Mature	Poor	Edge tree within group of 4 rows. Restricted, one-sided crown.		
1772	Sitka spruce	26	600	Mature	Poor	Edge tree within group of 4 rows. Restricted, one-sided crown.		
1773	Sitka spruce	14	350	Mature	Poor	Edge tree within group of 4 rows. Restricted and suppressed, one-sided crown.		
1774	Sitka spruce	26	650	Mature	Fair	Edge tree within group of 4 rows. Dense, one-sided crown.		
1775	Sitka spruce	26	650	Mature	Fair	Edge tree within group of 4 rows. Dense, one-sided crown.		
1776	Sitka spruce	25	650	Mature	Fair	Edge tree within group of 4 rows. Dense, one-sided crown.		

Group / Tag	Species	Ht (m)	Dia (mm)	Age Class	Condition	Comments	Recommendations	Timescale
1777	Sitka spruce	25	650	Mature	Fair	Edge tree within group of 4 rows. Dense, one-sided crown.		
1778	Sitka spruce	24	500	Mature	Poor	Edge tree within group of 4 rows. Restricted, one-sided crown.		
1779	Sitka spruce	24	450	Mature	Poor	Edge tree within group of 4 rows. Dense, one-sided crown.		
1780	Sitka spruce	26	800	Mature	Fair	Edge tree within group of 4 rows. Dense, one-sided crown.		
1781	Sitka spruce	26	800	Mature	Fair	Edge tree within group of 4 rows. Dense, one-sided crown.		
1782	Sitka spruce	24	350	Mature	Poor	Edge tree within group of 4 rows. Restricted, one-sided crown.		
1783	Sitka spruce	25	420	Mature	Poor	Edge tree within group of 4 rows. Restricted, one-sided crown.		
1784	Sitka spruce	24	370	Mature	Poor	Edge tree within group of 4 rows. restricted, one-sided crown.		
1785	Sitka spruce	26	800	Mature	Fair	Edge tree within group of 4 rows. Dense, one-sided crown.		
1786	Whitebeam	10	400	Mature	Fair	Edge tree within group of 4 rows. One-sided crown.		
1787	Sitka spruce	24	330	Mature	Poor	Within group of 4 rows. Restricted spread with no live lower branches.		
1788	Sitka spruce	20	270	Mature	Poor	Within group of 4 rows. Very restricted spread with no live lower branches.		
1789	Sitka spruce	25	520	Mature	Poor	Within group of 4 rows. Restricted spread with few live lower branches.		

Group / Tag	Species	Ht (m)	Dia (mm)	Age Class	Condition	Comments	Recommendations	Timescale
1790	Sitka spruce	24	320	Mature	Poor	Within group of 4 rows. Restricted spread with few live lower branches.		
1791	Sitka spruce	15	250	Mature	Poor	Within group of 4 rows. Very restricted spread with no live lower branches.		
1792	Sitka spruce	26	900	Mature	Fair	End tree within group of 4 rows. Dense, one-side crown.		
1793	Sitka spruce	25	650	Mature	Poor	Within group of 4 rows. Restricted spread with no live lower branches.		
1794	Sitka spruce	22	250	Mature	Poor	Within group of 4 rows. Restricted spread with no live lower branches.		
1795	Sitka spruce	25	400	Mature	Poor	Within group of 4 rows. Restricted spread with no live lower branches.		
1796	Sitka spruce	20	270	Mature	Poor	Within group of 4 rows. Restricted spread with no live lower branches.		
1797	Sitka spruce	24	380	Mature	Poor	Within group of 4 rows. Restricted spread with no live lower branches.		
1798	Sitka spruce	25	380	Mature	Poor	Within group of 4 rows. Restricted spread with no live lower branches.		
1799	Sitka spruce	25	400	Mature	Poor	Within group of 4 rows. Restricted spread with no live lower branches.		
1800	Sitka spruce	24	450	Mature	Poor	Within group of 4 rows. Restricted spread with few live lower branches.		
801	Sitka spruce	24	310	Mature	Poor	Within group of 4 rows. Restricted spread with no live lower branches.		
802	Sitka spruce	25	340	Mature	Poor	Within group of 4 rows. Restricted spread with no live lower branches.		

Group / Tag	Species	Ht (m)	Dia (mm)	Age Class	Condition	Comments	Recommendations	Timescale
803	Sitka spruce	25	360	Mature	Poor	Within group of 4 rows. Restricted spread with no live lower branches.		
804	Sitka spruce	25	450	Mature	Poor	Within group of 4 rows. Restricted spread with no live lower branches.		
805	Sitka spruce	25	350	Mature	Poor	Within group of 4 rows. Restricted spread with few live lower branches. Tight fork at 3m forming 2 co-dominant leaders.		
806	Sitka spruce	26	500	Mature	Poor	Within group of 4 rows. Restricted spread with no live lower branches.		
807	Sitka spruce	25	470	Mature	Poor	Within group of 4 rows. Restricted spread with no live lower branches.		
808	Sitka spruce	26	650	Mature	Poor	Within group of 4 rows. Restricted spread with few live lower branches.		
809	Sitka spruce	25	400	Mature	Poor	Within group of 4 rows. Restricted spread with few live lower branches.		
810	Sitka spruce	27	700	Mature	Poor	At edge of group of 4 rows. Restricted spread with one-sided crown.		
811	Sitka spruce	26	620	Mature	Poor	At edge of group of 4 rows. Restricted spread with one-sided crown.		
812	Sitka spruce	26	600	Mature	Poor	At edge of group of 4 rows. Restricted spread with one-sided crown.		
813	Sitka spruce	20	440	Mature	Poor	At edge of group of 4 rows. Restricted spread with one-sided crown.		
814	Sitka spruce	25	580	Mature	Poor	At edge of group of 4 rows. Restricted spread with one-sided crown.		
815	Sitka spruce	25	570	Mature	Poor	At edge of group of 4 rows. Restricted spread with one-sided crown.		

Group / Tag	Species	Ht (m)	Dia (mm)	Age Class	Condition	Comments	Recommendations	Timescale
816	Sitka spruce	8	220	Semi mature	Dead	At edge of group of 4 rows. Small standing dead.		
817	Sitka spruce	27	750	Mature	Poor	At edge of group of 4 rows. Restricted spread with one-sided crown. Swollen butt.		
818	Sitka spruce	26	650	Mature	Poor	At edge of group of 4 rows. Restricted spread with one-sided crown.		
819	Sitka spruce	25	520	Mature	Poor	At edge of group of 4 rows. Restricted spread with one-sided crown.		
820	Sitka spruce	26	660	Mature	Poor	At edge of group of 4 rows. Restricted spread with one-sided crown.		
821	Sitka spruce	24	450	Mature	Poor	At edge of group of 4 rows. Restricted spread with one-sided crown.		
822	Sitka spruce	26	630	Mature	Poor	At edge of group of 4 rows. Restricted spread with one-sided crown.		
823	Sitka spruce	26	600	Mature	Poor	At edge of group of 4 rows. Restricted spread with one-sided crown.		
824	Sitka spruce	26	650	Mature	Poor	At edge of group of 4 rows. Restricted spread with one-sided crown.		
825	Sitka spruce	25	450	Mature	Poor	At edge of group of 4 rows. Restricted spread with one-sided crown.		
826	Sitka spruce	23	320	Mature	Poor	At edge of group of 4 rows. Restricted spread with one-sided crown.		
827	Sitka spruce	27	750	Mature	Poor	At edge of group of 4 rows. Restricted spread with one-sided crown.		
828	Sitka spruce	26	680	Mature	Poor	At edge of group of 4 rows. Restricted spread with one-sided crown.		

Group / Tag	Species	Ht (m)	Dia (mm)	Age Class	Condition	Comments	Recommendations	Timescale
829	Sitka spruce	25	400	Mature	Poor	At edge of group of 4 rows. Restricted spread with one-sided crown.		
830	Sitka spruce	22	390	Mature	Poor	At edge of group of 4 rows. Restricted spread with one-sided crown.		
831	Sitka spruce	27	750	Mature	Poor	At edge of group of 4 rows. Restricted spread with one-sided crown.		
832	Sitka spruce	23	380	Mature	Poor	At edge of group of 4 rows. Restricted spread with one-sided crown.		
833	Sitka spruce	26	480	Mature	Poor	At edge of group of 4 rows. Restricted spread with one-sided crown.		
Strip of mature trees lining track adjacent to driving range								
834	Wych elm					Has been removed due to Dutch Elm Disease	Tree Planting Opportunity	
835	Ash	19	780	Mature	Poor	In row lining track. Overhanging path next to club house and outside dining tent erected during Covid pandemic. Increased ground level at base. Top dieback. Minor bark death at base. Minor deadwood. Inonotus fungal bracket previously noted in upper crown. At increased exposure to wind following removal of adjacent elms. Crown has been reduced by around 25%. ADD Class 1.	Monitor for Ash Dieback Disease	
836	Ash	20	900	Mature	Poor	In row lining track. Overhanging outside dining tent erected in during Covid pandemic. Fork at 2m forming 3 co-dominant stems. Increased ground level at base. Patch of canker at 6m. Moderate deadwood. Pholiota fungal bodies at base. At increased exposure following removal of dead elms. Crown has been reduced by around 25%. Co-dominant stem with bias toward dining tent has been pruned off. ADD Class 1.	Monitor for Ash Dieback Disease	
837	Wych elm					Has been removed due to Dutch Elm Disease	Tree Planting Opportunity	

Group / Tag	Species	Ht (m)	Dia (mm)	Age Class	Condition	Comments	Recommendations	Timescale
838	Ash	20	780	Mature	Poor	In row lining track. Adjacent to outside dining tent erected during Covid pandemic. Increased ground level at base. Moderate deadwood. Has recently snapped a large branch. At increased exposure following the removal of dead elms. Crown has been reduced by around 25%. ADD Class 1.	Monitor for Ash Dieback Disease	
839	Wych elm					Removed due to infection with Dutch Elm Disease.	Tree Planting Opportunity	
840	Wych elm					Removed due to infection with Dutch Elm Disease.	Tree Planting Opportunity	
841	Wych elm					Removed due to infection with Dutch Elm Disease.	Tree Planting Opportunity	
842	Wych elm					Removed due to infection with Dutch Elm Disease.	Tree Planting Opportunity	
843	Ash	22	750	Mature	Poor	In row lining track. Decaying stub at 5m. Trunk likely to be significantly hollow below this point. Tight fork at 3m. Low vigour with thinning top and moderate deadwood. At increased exposure following removal of dead elms. Crown has been reduced by around 25%. ADD Class 1.	Monitor for Ash Dieback Disease	
844	Ash	20	780	Mature	Poor	In row lining track. Minor deadwood. At increased exposure following removal of dead elms. Crown has been reduced by around 25%. ADD Class 1.	Monitor for Ash Dieback Disease	
845	Wych elm					Has been removed due to Dutch Elm disease.	Tree Planting Opportunity	
846 Group	Sycamore					7 in a row adjacent to car park. Planting opportunity within gaps.	Tree Planting Opportunity	

Group / Tag	Species	Ht (m)	Dia (mm)	Age Class	Condition	Comments	Recommendations	Timescale
847	Ash	20	750	Mature	Fair	In row lining track. Tips overhanging car park spaces. Swellings and epicormics on lower trunk. Moderate deadwood. Slight bias away from car park. At increased exposure following removal of dead elms. Crown has been reduced by around 25%. ADD Class 1.	Monitor for Ash Dieback Disease	
848	Ash	19	750	Mature	Poor	In row lining track. Large limb overhanging car park spaces. Large cavity at <2m. Sparse crown of low vigour with significant tip dieback. Moderate deadwood. Crown has been reduced by around 25%. ADD Class 1.	Monitor for Ash Dieback Disease	
849	Sycamore	9	350	Semi-mature	Fair	Developing well next to stump of elm. Young ash near base.	Tree Planting Opportunity	
850	Scots pine	22	500	Mature	Poor	Within small group of similar adjacent to car park. Sparse with restricted spread.		
851	Scots pine					Has been removed due to severe storm damage.		
852	Larch	9	280	Early mature	Poor	Within small group of similar adjacent to car park. Restricted spread with pronounced bias away from car park.		
853	Scots pine	23	420	Mature	Fair	Within small group of similar adjacent to car park. Straight trunk. Restricted spread with no lower branches.		
854	Scots pine	22	500	Mature	Fair	Within small group of similar adjacent to car park. Straight trunk. Reasonable form. Fairly sparse.		